

Message

From: Schmittdiel, Paula [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=0EC9C256420E48469663FF21FBC6A06F-SCHMITTDIEL, PAULA]
Sent: 6/18/2013 7:33:24 PM
To: Steve H. Singer [ssinger@PWT.COM]
Subject: RE: VB I-70 OU2

I'll try and follow up with Lisa to see if we can get them sampled.

Paula Schmittdiel
Remedial Project Manager
U.S. Environmental Protection Agency
1595 Wynkoop St.
Denver, CO 80202
Office: 303-312-6861
Cell: 720-951-0795

From: Steve H. Singer [mailto:ssinger@PWT.COM]
Sent: Tuesday, June 18, 2013 1:18 PM
To: Schmittdiel, Paula; Schmidt, Andrew
Subject: RE: VB I-70 OU2

Yes, we specifically asked the following questions:
Are the wells all still there?
Were they surveyed?

The question that we did not ask was whether they thought they would be destroyed during construction.

The CTL person did not have any answers and Lisa was trying to confuse these wells with the ones that PWT was sampling. We definitely asked CTL to look into it and Paula sent reference to the wells in her email after the meeting, suggesting that we may want to sample them.

From: Schmittdiel, Paula [mailto:Schmittdiel.Paula@epa.gov]
Sent: Tuesday, June 18, 2013 12:34 PM
To: Schmidt, Andrew
Cc: Steve H. Singer
Subject: RE: VB I-70 OU2

I think they did and CTL Thompson didn't think they were still there. Steve – is that correct?

Paula Schmittdiel
Remedial Project Manager
USEPA
1595 Wynkoop St.
Denver, CO 80202-1129

From: Schmidt, Andrew
Sent: Tuesday, June 18, 2013 12:27 PM
To: Schmittdiel, Paula; Steve H. Singer
Subject: RE: VB I-70 OU2

Paula,

I forgot to ask, did those wells come up in the meeting with CCoD?

Thanks!

AS

Andrew P. Schmidt, P.G.
Regional Superfund Hydrogeologist
US EPA Region 8, 8EPR-S
1595 Wynkoop St.
Denver, CO 80202
303.312.6283

Please consider the environment before printing this email.

From: Schmittdiel, Paula
Sent: Tuesday, June 18, 2013 11:30 AM
To: Steve H. Singer; Schmidt, Andrew
Subject: RE: VB I-70 OU2

Should we consider having these wells sampled prior to construction? I would think they would likely need to be investigated to determine if they needed development?

Paula Schmittdiel
Remedial Project Manager
USEPA
1595 Wynkoop St.
Denver, CO 80202-1129

From: Steve H. Singer [<mailto:ssinger@PWT.COM>]
Sent: Tuesday, June 18, 2013 11:23 AM
To: Schmidt, Andrew
Cc: Schmittdiel, Paula
Subject: RE: VB I-70 OU2

Hi Andrew, I don't believe there has been any aquifer testing done in OU2. I would agree that any dump related material would probably be higher hydraulic conductivity. On a related note, I was out at OU2 recently and believe that I have found the three wells that are located on CCoD property. They are CTLMW004, CTLMW005 and CTLMW006 on the maps I handed out previously. I also think I found CTLMW001 and possible CTLMW002 but have not looked for CTLMW003 because it is on Pepsi property.

Steve

From: Schmidt, Andrew [<mailto:Schmidt.Andrew@epa.gov>]
Sent: Tuesday, June 18, 2013 7:43 AM
To: Steve H. Singer
Cc: Schmittdiel, Paula
Subject: VB I-70 OU2

Steve,

I can't recall if there have been any slug tests done for any of the wells in OU2 that might be in landfill material..... I'm curious with regards to potential bedding material for the SS project and the hydraulic conductivity that that bedding material might have relative to the landfill material.

If we don't have slug test data (I don't think we do), my intuition would be that landfill debris would have a fairly high hydraulic conductivity. What do you think?

Thanks!

AS

*Andrew P. Schmidt, P.G.
Regional Superfund Hydrogeologist
US EPA Region 8, 8EPR-S
1595 Wynkoop St.
Denver, CO 80202
303.312.6283*

Please consider the environment before printing this email.